Highways/RoW Matters referred to FixMyStreet:
Progress Tracker

Fix My Street Ref:	Meeting Date	Minute Ref	Detail	By Whom	Due Date	Actions update	Revised Date	Status
4624046	11/05/2023	23.05.16	Blind 90º bend with no chevron markings or barriers This bend is on a very narrow road used by heavy farm vehicles and some delivery lorries as well as village traffic. The high hedge around Hemington House makes it impossible to see oncoming traffic from either direction. The bend is very steep and has no signs, markings or warnings. There has been an injury accident here. Chevron marking signs or similar should be installed.	Clerk	n/a	Status investigating - 2/6/23 Investigation: Ongoing - Thank you for your query. This will be investigated further and then a response made. No usual responses re progress - chase email sent to Highways Liaison 02/11/23 Response received advising that status is now 'Investigating'		**In-progress**
5244924	09/11/2023	23.11.11a	1. wooden 5 bar gate, multiple unsuitable catches, drags on ground meaning you have to get off a horse to lift it open, it doesn't open very wide to get a horse through, metal protrusions for a horse or rider to cut itself on.	Clerk		Investigating		**In-progress**
5244938	09/11/2023	23.11.11a	2. metal 5 bar gate, multiple unsuitable catches, often overgrown, gate drops making it very tricky to close from horseback.	Clerk		Investigating Investigation: Completed (Defect Found) - We can confirm that works have now been instructed for bridle gates to be installed along this route.		**In-progress**