Highways/RoW Matters referred to FixMyStreet:
Progress Tracker

Fix My Street Ref:	Meeting Date	Minute Ref	Detail	By Whom	Due Date	Actions update	Revised Date	Status
4624046	11/05/2023	23.05.16	Blind 90º bend with no chevron markings or barriers This bend is on a very narrow road used by heavy farm vehicles and some delivery lorries as well as village traffic. The high hedge around Hemington House makes it impossible to see oncoming traffic from either direction. The bend is very steep and has no signs, markings or warnings. There has been an injury accident here. Chevron marking signs or similar should be installed.	Clerk	n/a	Status investigating - 2/6/23 Investigation: Ongoing - Thank you for your query. This will be investigated further and then a response made. No usual responses re progress - chase email sent to Highways Liaison 02/11/23 Response received advising that status is now 'Investigating'		**In-progress**
5244924	09/11/2023	23.11.11a	1. wooden 5 bar gate, multiple unsuitable catches, drags on ground meaning you have to get off a horse to lift it open, it doesn't open very wide to get a horse through, metal protrusions for a horse or rider to cut itself on.	Clerk		Investigating New gate now fitted		**Closed**
5244938	09/11/2023	23.11.11a	2. metal 5 bar gate, multiple unsuitable catches, often overgrown, gate drops making it very tricky to close from horseback.	Clerk		Investigating Investigation: Completed (Defect Found) - We can confirm that works have now been instructed for bridle gates to be installed along this route.		**In-progress**
5456117	11/01/2024	24.01.11a	This gate was repaired in the last 12 months, but has 2 weights to keep closed which means it is very heavy to open and snaps shut dangerously quickly. It is on bridleway NY004 and on horseback is extremely hard to open and not possible to pass through without dismounting.	Clerk	19/01/2024	Investigating 17/1/24 Investigation: Completed (Reported to a third party) - We can confirm that the landowner has been contacted regarding this matter. Second weight to be removed from the bridle gate within the next 28 days. Second weight removed but catch stiil hard to open - update posted by Cllr Strelczuk.		**In-progress**

Highways/RoW Matters referred to FixMyStreet:
Progress Tracker

Fix My Street Ref:	Meeting Date	Minute Ref	Detail	By Whom	Due Date	Actions update	Revised Date	Status
5456169	11/01/2024	24.01.11a	The markings of this junction are badly worn. Traffic coming down Main Street (from Lutton direction) is supposed to give way, but to those not familiar with the road this is not clear. Vehicles have been seen to proceed towards Barnwell/Polebrook without stopping at this junction. White lines and a Give Way sign on the road are required. A pole with a Give Way sign is NOT requested as this would detract from the rural setting.	Clerk	19/01/2024	Investigating 17/1/24 Investigation: Completed (Defect Found), Defect Repair: Not Started - The area has been inspected and depending on weather conditions we hope for the work to be carried out within the next 28 days. You will receive further information when this job is completed. 08/02/24 Noted Completed, confirmed by Chairman		Closed
5600961	19/02/2024	24.01.11a	The drain is a soakaway at the roadside opposite Gypsy Lane but a few metres towards Hemington. The tree in the photi will position it. This has been a problem for some time and various efforts to fix it have failed. With the rain volumes in recent months, the problem is more acute. PS. Water has subsided in the photos - often the puddle/flood is right across the road.	Clerk	19/02/2024	Investigating Investigation complete - defect found 26/2/24 Work to clear drains now completed.		Closed